


FRYING PAN LANE



Command= 210-Point#, Start#-End# or G#= 1-100 Northing Distance Elev Descrip Pnt. Easting Type ---01-17-2025----09:26:23--------D:...\BMHOME9 4865.6033 5028.7261 50.00 1 SETHUB 46.00 2 4807.3221 5092.9958 SETHUB TRA 3 51.31 FNDDH 4985.2345 5232.0764 SS 52.86 4 4966.3332 5143.5966 FNDDH SS 50.55 **EPDRWL** 5 4937.5730 5075.0328 SS 50.29 6 4930.1603 5059.5774 SS EPDRWL 7 52.80 FNDDH 4882.6966 4952.7554 SS 50.69 26"OAK 8 4995.9445 4864.8616 SS 50.31 BLDR** 9 4847.2361 5043.0950 SS 49.68 FLAGPOLE 10 4862.1729 5037.9061 SS 48.61 11 4837.4567 5016.5688 EDGWDS SS 46.35 40"OAK 12 4796.4694 5042.5373 SS 47.21 STRING 13 4796.4691 4967.6783 SS 44.44 STRING 14 4759.7824 4984.1924 SS 41.41 STRING 15 4734.0534 4996.0395 SS 50.65 4859.9240 5091.1182 CORGAR 16 SS 51.60 4869.8542 5115.7624 CORGAR 17 SS 50.84 18 4893.5241 5072.4284 EPDR SS 50.39 5079.3016 EPDR 19 4860.5233 SS 41.77 DECK** 20 4774.3039 5106.6466 SS 4786.0076 5103.4722 42.48 DECK** 21 SS 42.82 4790.8681 5119.2137 DCK/POOL 22 SS 42.62 23 4800.0826 5130.9388 @POOL SS 42.71 @POOL 24 4779.6662 5141.2414 SS PIN-UP3 25 4612.3835 5036.3568 33.12 SS 35.33 HYDR??? 26 4691.3328 5124.3410 SS 38.40 COPTHEWD 27 4726.0352 5116.4755 SS 40.47 4761.1007 5092.1018 EWDS@BOA 28 SS 43.93 EWDSCOR 29 4791.2077 5079.6551 SS 49.87 30 4835.3901 5100.8639 CORHSE SS 48.06 PORCH 31 4839.5078 5153.8369 SS 49.23 32 4845.4982 5168.9180 PORCH SS 50 4892.7452 4975.8258 TRA 51 5143.5966 4966.3332 TRA 52 4985.2307 5232.1016 TRA 53 4746.9526 5346.6918 TRA 54 4666.3409 5159.5884 TRA 5036.7184 55 4613.6788 TRA


56

4882.7630

4952.9080


INT

Point#, Start#-End# or G#= 4-



05557 77 HAR 17 ALL: 36 REC'D ROCKMOUND COUNT REGISTRY OF DEEDS

Ŋ



Tocky B.

From:

"Tocky B." <stockton@ttlc.net>
<thomas.baker@vsea.com>

To: Sent:

Friday, January 06, 2012 9:37 AM

Attach:

602WASSON TO TOM BAKER 01-06-12 REV.pdf

Subject:

Re: Assistance

How's this? Tocky

---- Original Message ----

From: thomas.baker@vsea.com

To: stockton@ttlc.com

Sent: Friday, January 06, 2012 7:26 AM

Subject: Assistance

Tarkey,

You may or may not remember, but some time ago Tom Wasson had you do a brief survey to site a garage on my property at 10 Frying Pan Lane in Hampton Falls. As you probably suspected, the ZBA declined my request for a variance. So now I have to relocate the garage.

I was hoping that I could hire you again to help me find an acceptable location for the building.

If you would like to do this, please call me at 978-580-9836 or 603-778-6099 and we can set up a time.

If possible, I would like to do before we get a bunch of snow (I know, I'm living on borrowed time - but Mother Nature has been working with me this winter).

Tom

Thomas C. Baker

Vice President Finance | Varian Semiconductor Equipment | Silicon Systems Group | Applied Materials Office: 978.282.2301 | Mobile: 978.580.9836

The content of this message is Applied Materials Confidential. If you are not the intended recipient and have received this message in error, any use or distribution is prohibited. Please notify me immediately by reply e-mail and delete this message from your computer system. Thank you.

🗲 Save paper and trees. Please consider the environment before printing this e-mail.